

Borehole Information

Borehole Number:

105/21/X001/H1

Prospecting Company: De Beers Holdings Botswana

Prospecting License No.: PL78/88

Coordinates Type: WGS 84

Coordinates Format: Decimal Degrees

Coordinates: N/A

Location: Ghanzi

Start Drill: N/A

End Drill: N/A

Borehole Type: Exploration

Drilling Method: Core

Sample Type: Core

Depth of Surface Casing: N/A

Azimuth: Degrees

Hole Inclination: N/A

Collar Elevation: N/A

Borehole Water Strike: N/A

End of Hole (Depth): N/A

Log Formation:

No.	From (m)	To (m)	Log Formation
1.	0	30	Loose Kalahari sand, no chips recovered.
2.	0	30	U Kalahari - loose Kalahari Sands. No chips recovered.
3.	30	70	L Kalahari - as above but slightly calcretised very poor chips recovered.
4.	70	90	Karoo - pale pink fine to very fine grained Sandstone with siltstone bands mottled in places.
5.	90	110	Karoo - alteration of very fine, occasionally Conglomerateeratic Sandstone and laminated mudstone.
6.	110	200	Karoo - green grey medium to coarse grained dolerite ? A poorly developed Schistone fabric can be seen throughout.

NB: For any enquiries, application, acquisition or verifications related to Water Boreholes, kindly contact the Department of Water and Sanitation for assistance.

